


ireplacement parts industries, inc.

Call (800) 221-9723 • FAX (818) 882-7028 • EMAIL order@rpiparts.com

Fits AUTOCRIT & MICRO-HEMATOCRIT



RPI Part #CAM115 OEM Part #42055801 (Old OEM Part #0551-600-000)

MOTOR & SPINDLE ASSEMBLY


- 120VAC, 60 Hz.
- 11,700 RPM (+22%, -10%)



MOTOR MOUNTING PLATE RPI Part #CAM049B

Fits: Motor & Spindle Assembly

Fits AUTOCRIT II & MICRO-HEMATOCRIT II



RPI Part #CAM115 OEM Part #42055801 (Old OEM Part #0558-600-00)

MOTOR & SPINDLE ASSEMBLY


- 120VAC, 60 Hz.
- 11,700 RPM (+22%, -10%)



LOWER CHASSIS COVER PLATE RPI Part #CAM115B

Fits: Chassis

Fits AUTOCRIT ULTRA III & MICRO-HEMATOCRIT ULTRA III



RPI Part #CAM115 OEM Part #42055801 (Old OEM Part #0575-600-000)

MOTOR & SPINDLE ASSEMBLY

- 120VAC, 60 Hz.
- 11,700 RPM (+22%, -10%)



MOTOR MOUNTING PLATE RPI Part #CAM050B

Fits: Motor & Spindle Assembly



LOWER CHASSIS COVER PLATE RPI Part #CAM115B

Fits: Chassis

Important Note Regarding Autocrit and Micro-Hematocrit: The head adapter on the old style RPI motors that fit the Autocrit and Micro-Hematocrit can not be removed to allow reuse of the mounting plate. So when replacing the old style RPI Motor Assembly (RPI Part #CAM049) with the new style (RPI Part #CAM115), you will need to replace the round style mounting plate. RPI provides a new round style mounting plate free of charge when you order the the new style Motor Assembly (RPI Part #CAM115).

Important Note Regarding the Autocrit II and Micro-Hematocrit II: The head adapter on the old style RPI motors that fit the Autocrit II and Micro-Hematocrit II can not be removed to allow reuse of the mounting plate. So when replacing the old style RPI Motor Assembly (RPI Part #CAM050) with the new style (RPI Part #CAM115), you will need to replace the lower chassis cover plate. RPI provides a new lower chassis cover plate free of charge when you order the the new style Motor Assembly (RPI Part #CAM115).

Important Note Regarding the Autocrit III and Micro-Hematocrit III: You will need to replace the triangular style mounting plate and a lower chassis cover plate. RPI provides new plates free of charge when you order the new style Motor Assembly (RPI Part #CAM115).